## UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.

: 6,948,966 B2

Page 1 of 1

APPLICATION NO.: 09/988161

INVENTOR(S)

: September 27, 2005 : Ko KAMBAYASHI et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Titel Page, Column 2 (Other Publications), Line 1, delete "ACII" and insert -- ASCII -therefor.

Column 8, Line 57, delete "connecter" and insert -- connector -- therefor.

Column 8, Line 58, delete "net" and insert -- not -- therefor.

Column 9, Line 1, delete "connecter" and insert -- connector -- therefor.

Column 9, Line 16, delete "connecter" and insert -- connector -- therefor.

Column 12, Line 1, delete "fasteners" and insert -- fasteners, -- therefor.

Signed and Sealed this

Fifteenth Day of August, 2006

JON W. DUDAS Director of the United States Patent and Trademark Office